



رقم الاستمارة: 120

استمارة فحص مبنى

التاريخ	7 يونيو 2023م	النشاط	روضة <input type="checkbox"/>	مدرسة <input checked="" type="checkbox"/>	معهد تعليمي <input type="checkbox"/>
اسم صاحب الطلب	المدرسة الهندية الجديدة				
عنوان المبنى المقترح	رقم	129	طريق	4104	مجمع
	941	المنطقة	الرفاع الشرقي		

نتائج الفحوصات Tests Results								
تقييم الفحص Test Evaluation					نوع التحليل/الفحص المطلوب Required Inspection/Test	عمر المبنى Age of the Building		
<input type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Bad	Visual Inspection	أقل من 15 سنة Less than 15 years	<input type="checkbox"/>	
<input type="checkbox"/> Excellent	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Bad	Schmidt Rebound Hammer Test	من 15 – 30 سنة 15 – 30 years	<input type="checkbox"/>	
<input type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Bad	Compressive Strength of Concrete	أكثر من 30 سنة More than 30 years	<input type="checkbox"/>	
<input type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Bad	Depth of Carbonation of Concrete			
<input type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Bad	Chemical Analysis- Chloride & Sulphates B.S 1881			
<input type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Bad	Half Cell - Electro Potential Test			
<input type="checkbox"/> Excellent	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Poor	<input type="checkbox"/> Bad	Cover Meter Survey			

رأي الشركة الاستشارية	<input type="checkbox"/>	صالح للاستخدام لمدة لا تقل عن (3) سنوات بعد عمل صيانة	<input type="checkbox"/>	غير صالح للاستخدام	<input type="checkbox"/>
-----------------------	--------------------------	---	--------------------------	--------------------	--------------------------

ملاحظة: ارفاق المستندات الداعمة لعمر المبنى والفحوصات والصور مع توضيح تفصيلي لنطاق عمل الصيانة المطلوبة (إن وجدت)

اسم الشركة الاستشارية Consultant Name	City Engineering Bureau
التاريخ Date	12 Sep 23
التوقيع Signature	

(يتحمل المكتب الهندسي صحة البيانات الواردة في الاستمارة، ويتحمل المسؤولية القانونية على ما يترتب عليها من آثار)



CR. No.20115-1

VAT No. 220006153900002

Building 438, Road 2809, Block 328

Oman Avenue, Segaya

Kingdom of Bahrain

Ref. CE/FMP/TNIS/014_23

31 May 2023

To Whom It May Concern:

Project: The New Indian School- Riffa

Subject: Structural Stability Certificate

Dear Sir,


Reference is made to the above existing building **The New Indian School** at **Riffa** and upon owners request, We, City Engineering, being the design and supervision Consultant for the said project, herein certify that a thorough inspection and survey has been carried out for the main building, for both structural and functional aspects, and found satisfactory, and until the present recorded status, the said building is considered very sound for structural point of view and will continue to perform and serve the purpose as a school for at least 3 coming years without any foreseen problems.

This certificate has been issued upon the owner's request for whatever purpose it may serve.

Thank you.

Yours truly,

Majeed Al Sayed
Managing Director



CITY ENGINEERING BUREAU

P.O. Box: 33343, Manama, Kingdom of Bahrain

Tel.: +973 1725 5322, +973 1726 0660

Fax: +973 1724 2545

Email: info@ceb-bh.com / cityeng@batelco.com.bh

Web: ceb-bh.com