Ministry of Education اردَّ الْمَرْيَنَةِ وَالْمَاكِينَةِ وَالْمَرْيِنَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَرْيِنَةِ وَالْمَاكِينَةِ وَلْمَاكِينَةً وَالْمَاكِينَةِ وَالْمَلْكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَلْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَةِ وَالْمَاكِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَةِ وَلِيْعِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَاقِ وَالْمَالِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَالِينَاقِ وَالْمَاكِينَاقِ وَالْمَالْمِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَاقِ وَالْمَاكِينَاقِ وَلْمَاكِينَاقِ وَالْمَاكِينَالِي وَالْمَاكِينَالِي وَالْمَاكِيلِيْ												
	120	رقم الاستمارة:		استمارة فحص مبني								
	معهدتعليمي		🗵 مدرسة		ا روضة		النشاط	7 يونيو 2023م		الناريخ 7		
							مة الهندية الجديدة			اسم صاحب الطلب المدره		
	رفاع الشرقي	المنطقة ال	941	مجمع	4104		طربق	129	رقم	وان المبنى المقترح رقم		
	نتانج الفعوصات Tests Results عمرالمبنى نوع التحليل/الفحص المطلوب تقييم الفحص Test Evaluation Required Inspection/Test Age of the Building											
	Excellent	Good	st Evaluati	Poor	Bad	Required Inspection/Test Visual Inspection		à:	Age of the Bunding اقل من 15 سنة Less than 15 years			
	Excellent	Good	☐ Fair	Poor	Bad	Schmidt Rebound Hammer Test		it i	من 15 – 30 سنة 15 – 30 years			
	Excellent	Good	☐ Fair	Poor	☐ Bad	Compressive Strength of Concrete						
	Excellent	Good	☐ Fair	Poor	Bad	Depth of Carbonation of Concrete						
	Excellent	Good	☐ Fair	Poor	Bad	Cher	Chemical Analysis- Chloride & Sulphates B.S 1881		1	اکثر من 30 سنة More than 30 years		
	Excellent	Good	☐ Fair	Poor	Bad	Half Cell - Electro Potential Test Cover Meter Survey		t				
	Excellent	Good	☐ Fair	Poor	Bad							
رأي الشركة الاستشارية عن (3) سنوات عن (3) سنوات بعد عمل صيانة												
ملاحظة: ارفاق المستندات الداعمة لعمر المبنى والفحوصات والصور مع توضيح تفصيلي لنطاق عمل الصيانة المطلوبة (إن وجدت)												
City Engineering Burary Consultant Name												
City Engineering Bureau Consultant Name OF Space 2023 Date												





CR. No.20115-1

VAT No. 220006153900002 Buillding 438, Road 2809, Block 328 Oman Avenue, Segaya Kingdom of Bahrain

> Ref. CE/FMP/TNIS/014_23 31 May 2023

To Whom It May Concern:

Project:

The New Indian School-Riffa

Subject:

Structural Stability Certificate

Dear Sir,

Reference is made to the above existing building **The New Indian School** at **Riffa** and upon owners request, We, City Engineering, being the design and supervision Consultant for the said project, herein certify that a thorough inspection and survey has been carried out for the main building, for both structural and functional aspects, and found satisfactory, and until the present recorded status, the said building is considered very sound for structural point of view and will continue to perform and serve the purpose as a school for at least 3 coming years without any foreseen problems.

This certificate has been issued upon the owner's request for whatever purpose it may serve.

Thank you.

Yours truly,

Majeed Al Sayed Managing Director

j

P.O. Box: 33343, Manama, Kingdom of Bahrain-

CITY ENGINEERING BUR

Tel.: +973 1725 5322, +973 1726 0660

Fax: +973 1724 2545

Email: info@ceb-bh.com / cit/eng@batelco.com.bh

Web: ceb-bh.com

